Message

From: Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MASSMAIL-

01/CN=RECIPIENTS/CN=JAMES.HANCHETT]

Sent: 2/27/2012 2:31:26 PM

To: 'Lobik Stephen' [slobik@facil.umass.edu]

Subject: AC/Heating Unit

Hi Steve,

The noise is back with a vengeance. It must be outside temperature dependent. Could you see if the contactor who installed it is responsible or is Johnson Controls?

Thanks,

Jim Hanchett
Amherst Drug Lab
Room N251 Morrill I
637 North Pleasant Street
Amherst, MA 01003
Phone 413-545-2607
Fax 413-545-2608
Cell